

Customer:	Email:	Date: 9-7-04
Address:	Phone (h):	County: Hennepin
City/State/Zip: Minneapolis/MN/55414	Phone (c):	Hudson:

PROBLEM

TEAR (#1) IN RUBBER MEMBRANE



TEAR (#2) IN RUBBER MEMBRANE



Customer:	Email:	Date: 9-7-04
Address:	Phone (h):	County: Hennepin
City/State/Zip: Minneapolis/MN/55414	Phone (c):	Hudson:

SOLUTION

STEP 1 - TEAR OFF & INSPECT ROOF DECKING



STEP 2— INSTALL 1/2" CDX UNDERLAYMENT



Customer:	Email:	Date: 9-7-04
Address:	Phone (h):	County: Hennepin
City/State/Zip: Minneapolis/MN/55414	Phone (c):	Hudson:

SOLUTION

STEP 3 - INSTALL HIGH DENSITY FIBERBOARD



STEP 4— INSTALL 60 MIL RUBBER ROOF MEMBRANE

